

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Date:

	JAN 7		
Reviewed:	11.	0	

Mine Name: Torrey Buff South	Permit Number: S/055/0022			
Operator Name: Quality Building Stone	Inspection Date: April 21, 2011			
Inspector(s): Wayne Western	Time: 8:00 – 9:10 AM			
Other Participants:	Mine Status: Active			
Elements of Inspection	Evaluated	Comment	Enforcement	
1. Permits, Revisions, Transfer, Bonds				
2 7 1 2 6 6 (1 6 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				

	Elements of Inspection	Lialuatea	Comment	Liniorcement
1.	Permits, Revisions, Transfer, Bonds			
2.	Public Safety (shafts, adits, trash, signs, highwalls)			
3.	Protection of Drainages / Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
6.	Concurrent Reclamation			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8.	Water Impoundments			
9.	Soils			
10.	Re-vegetation			
11.	Air Quality			
12.	Other			

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond amount is for \$14,000.00 and the renewal date is January 12, 2009. The permit fees have been paid for 2010.

The site was in stable condition.

There was no sign of recent activity on the site.

Conclusions and Recommendations:

The Division should require an increase in bond for escalation.


April 21. 2011 Page 2 of 4 S/055/0022

Inspector's Signature WHW


cc: (OPERATOR) Sue Fivecoat

O:\M055-Wayne\S0550022-HansenTorreyBuff\inspections\Insp-04212011.doc


Warper Wenter




Over look



Pit



Operational pit



Active pit